

Packing List



Successfully pass the free certification exam at IW Academy and become an Infinet Certified Engineer.

[To the certification exam](#)

This section describes the components that are supplied by default with the Quanta 70 family device.

Before the installation, please make sure you have all necessary parts and accessories.

Q70-39 packing list

- Outdoor unit (ODU).
- Power supply.
- Cable gland for Optical cable.
- Cable gland for Ethernet cable
- Shielded RJ-45 connector.
- Unshielded RJ-45 connector.
- RJ-45 plug cap.
- Mounting kit - universal assembling kit for mounting the ODU on standard pole, wall or thick pipe (vertical/horizontal).
- Power cord - the model depends on the region, according to the Purchase Order.

Q70-50 packing list

- Outdoor unit (ODU).
- Power supply.
- Cable gland for Optical cable.
- Cable gland for Ethernet cable
- Shielded RJ-45 connector.
- Unshielded RJ-45 connector.
- RJ-45 plug cap.
- Mounting kit assembled.
- Bolt M8x165 (x4).
- Bolt M8x50 (x2).
- Washer 8 flat (x6).
- Washer 8 spring (x6).
- Nut M8 (x6).
- Bracer (x2).
- Power cord - the model depends on the region, according to the Purchase Order.